

**Inspection Photos**  
**Location Name: Degenhart State AE 16-63HN**  
**Location ID: 423230**




**Photo 1 – Pumping Unit**



**Photo 2 – Tank Battery**



**Inspection Photos**  
**Location Name: Degenhart State AE 16-63HN**  
**Location ID: 423230**



**Photo 3 – Stained Soil at North Exhaust**




**Photo 4 – Stained Soil inside Engine House**





**Inspection Photos**  
**Location Name: Degenhart State AE 16-63HN**  
**Location ID: 423230**



**Photo 5 – Stained Soil inside Engine House**