

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/15/2019

Submitted Date:

11/15/2019

Document Number:

697000212**FIELD INSPECTION FORM**

Loc ID 337435 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10536Name of Operator: SMITH ENERGY LLCAddress: 1540 MAIN ST SUITE 218 #334City: WINDSOR State: CO Zip: 80550**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Chris	(970) 330-7034	smithenergy@live.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285770	WELL	PR	01/27/2009	GW	125-10196	S-Y KIRCHENSCHLAGER 13-28	PR

**General Comment:**

Routine Inspection

**Location****Lease Road:**

Type	Access		
comment:	Two track through pasture		
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease sign by meter shed		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by plastic tank		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Wire fence around wellhead, metal sheds and pit		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

<b>Inspected Facilities</b>				
Facility ID: 285770	Type: WELL	API Number: 125-10196	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing. Casing production			
Corrective Action:				Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: Location and access are grassed over

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT