

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2019

Submitted Date:

11/18/2019

Document Number:

689703787

FIELD INSPECTION FORM
 Loc ID 336048 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 100 CHEVRON USA INC

City: RANGELY State: CO Zip: 81648

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

26 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Sanford, Anita	(970) 675-3842	atlx@chevron.com	All Inspections
Colby, Lou		lou.colby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295998	WELL	WO	11/17/2015	GW	045-15897	SKR 598-36-BV-01	WO
297728	WELL	WO	11/17/2015	GW	045-16929	SKR 598-36-BV-22	WO
297729	WELL	WO	11/17/2015	GW	045-16930	SKR 598-36-BV-13	WO
297730	WELL	WO	11/17/2015	GW	045-16931	SKR 598-36-BV-15	WO
297731	WELL	WO	11/17/2015	GW	045-16932	SKR 598-36-BV-17	WO
297732	WELL	WO	11/17/2015	GW	045-16933	SKR 598-36-BV-19	WO
297733	WELL	WO	11/17/2015	GW	045-16934	SKR 598-36-BV-21	WO
297734	WELL	WO	11/17/2015	GW	045-16935	SKR 598-36-BV-09	WO
297735	WELL	WO	11/17/2015	GW	045-16936	SKR 598-36-BV-11	WO
297736	WELL	WO	11/17/2015	GW	045-16937	SKR 598-36-BV-07	WO
297737	WELL	WO	11/17/2015	GW	045-16938	SKR 598-36-BV-03	WO
297738	WELL	WO	11/17/2015	GW	045-16393	SKR 598-36-BV-05	WO
297739	WELL	WO	11/17/2015	GW	045-16939	SKR 598-36-BV-20	WO
297740	WELL	WO	11/17/2015	GW	045-16940	SKR 598-36-BV-18	WO
297741	WELL	WO	11/17/2015	GW	045-16941	SKR 598-36-BV-02	WO
297742	WELL	WO	11/17/2015	GW	045-16942	SKR 598-36-BV-16	WO
297743	WELL	WO	11/17/2015	GW	045-16943	SKR 598-36-BV-12	WO
297744	WELL	WO	11/17/2015	GW	045-16944	SKR 598-36-BV-04	WO
297745	WELL	WO	11/17/2015	GW	045-16945	SKR 598-36-BV-06	WO

297793	WELL	WO	11/17/2015	GW	045-16966	SKR 598-36-BV-10	WO
297794	WELL	WO	11/17/2015	GW	045-16967	SKR 598-36-BV-08	WO
297795	WELL	WO	11/17/2015	GW	045-16968	SKR 598-36-BV-14	WO

General Comment:

COGCC Inspection Report Summary

On Thursday 11/14/2019 at approximately 1500 hours, I, Inspector Mike Longworth, conducted a inspection at CHEVRON USA INC SKR 598-36-BV-01, Location # 336048 in Garfield County, Colorado.

During this inspection the following possible compliance issues were observed:

Sign is laying on the ground at entrance. No emergency service number (911) and nearest road on sign.

Install sign to comply with Rule 210.b.

C.A. Date 12/19/2019

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location**Lease Road:**

Type	Main		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	Sign is laying on the ground at entrance. No emergency service number (911) and nearest road on sign.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	No emergency service number (911) and nearest road on sign.		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 12/19/2019

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 295998 Type: WELL API Number: 045-15897 Status: WO Insp. Status: WO

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: The well was shut-in after drilling and is waiting on Completion.

Corrective Action: _____ Date: _____

Facility ID: 297728 Type: WELL API Number: 045-16929 Status: WO Insp. Status: WO

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: The well was shut-in after drilling and is waiting on Completion.

Corrective Action: _____ Date: _____

Facility ID: 297729 Type: WELL API Number: 045-16930 Status: WO Insp. Status: WO

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: The well was shut-in after drilling and is waiting on Completion.

Corrective Action: _____ Date: _____

Facility ID: 297730 Type: WELL API Number: 045-16931 Status: WO Insp. Status: WO

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: The well was shut-in after drilling and is waiting on Completion.

Corrective Action: _____ Date: _____

Facility ID: 297731 Type: WELL API Number: 045-16932 Status: WO Insp. Status: WO

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: The well was shut-in after drilling and is waiting on Completion.

Corrective Action: _____ Date: _____

Facility ID: 297732 Type: WELL API Number: 045-16933 Status: WO Insp. Status: WO

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: The well was shut-in after drilling and is waiting on Completion.

Corrective Action: _____ Date: _____

Facility ID: 297733 Type: WELL API Number: 045-16934 Status: WO Insp. Status: WO

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: The well was shut-in after drilling and is waiting on Completion.

Corrective Action: _____ Date: _____

Facility ID: 297734 Type: WELL API Number: 045-16935 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: The well was shut-in after drilling and is waiting on Completion.

Corrective Action: _____ Date: _____

Facility ID: 297735 Type: WELL API Number: 045-16936 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: The well was shut-in after drilling and is waiting on Completion.

Corrective Action: _____ Date: _____

Facility ID: 297736 Type: WELL API Number: 045-16937 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: The well was shut-in after drilling and is waiting on Completion.

Corrective Action: _____ Date: _____

Facility ID: 297737 Type: WELL API Number: 045-16938 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: The well was shut-in after drilling and is waiting on Completion.

Corrective Action: _____ Date: _____

Facility ID: 297738 Type: WELL API Number: 045-16393 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: The well was shut-in after drilling and is waiting on Completion.

Corrective Action: _____ Date: _____

Facility ID: 297739 Type: WELL API Number: 045-16939 Status: WO Insp. Status: WO

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: The well was shut-in after drilling and is waiting on Completion.

Corrective Action: _____ Date: _____

Facility ID: 297740 Type: WELL API Number: 045-16940 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: The well was shut-in after drilling and is waiting on Completion.

Corrective Action: _____ Date: _____

Facility ID: 297741 Type: WELL API Number: 045-16941 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: The well was shut-in after drilling and is waiting on Completion.

Corrective Action: _____ Date: _____

Facility ID: 297742 Type: WELL API Number: 045-16942 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: The well was shut-in after drilling and is waiting on Completion.

Corrective Action: _____ Date: _____

Facility ID: 297743 Type: WELL API Number: 045-16943 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: The well was shut-in after drilling and is waiting on Completion.

Corrective Action: _____ Date: _____

Facility ID: 297744 Type: WELL API Number: 045-16944 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: The well was shut-in after drilling and is waiting on Completion.

Corrective Action: _____ Date: _____

Facility ID: 297745 Type: WELL API Number: 045-16945 Status: WO Insp. Status: WO

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: Corrective Action:

Date: _____

Facility ID: 297793 Type: WELL API Number: 045-16966 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: Corrective Action:

Date: _____

Facility ID: 297794 Type: WELL API Number: 045-16967 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: Corrective Action:

Date: _____

Facility ID: 297795 Type: WELL API Number: 045-16968 Status: WO Insp. Status: WO**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: Corrective Action:

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Culverts	Pass			
Compaction	Pass					
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689703793	Inspection 689703787 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4990769