

Inspection Photos
Location Name: Kalia 5-11
Location ID: 302348




Photo 1 – Pumping Unit




Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Kalia 5-11
Location ID: 302348



Photo 3 – Stained Soil at Exhaust



Photo 2 – Stained at Gas Engine