

Inspection Photos
Location Name: Kalia 5-11 & DF Ranch Tank Battery
Location ID: 461153



Colorado Oil and Gas Conservation Commission
40.93619, -104.18072, 5240.4ft, 242°
11/14/2019 11:10:08



Colorado Oil and Gas Conservation Commission
40.93611, -104.18125, 5271.7ft, 218°
11/14/2019 11:10:54

Photo 1 – Pumping Unit

Photo 2 – Capacity Labels have faded no longer legible

Inspection Photos
Location Name: Kalia 5-11 & DF Ranch Tank Battery
Location ID: 461153




Photo 3 – Stained Soil at dumps on East Heater Treater




Photo 4 – Recycle Pump containment - Oily Waste and Wildlife protection devices not adequate