

Inspection Photos
Location Name: Everitt 14-32
Location ID: 302935



Photo 1 – Pumping Unit



Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Everitt 14-32
Location ID: 302935



Photo 3 – Stained Soil at Gas Engine



Photo 4 – Unused Wellhead parts