

Inspection Photos
Location Name: Everitt 14-32 and Pevler 14-22 Tank Battery
Location ID: 464351



Photo 1 – Tank Battery




Photo 2 – South Crude Oil Tanks – Capacity has faded no longer legible.

Inspection Photos

Location Name: Everitt 14-32 and Pevler 14-22 Tank Battery

Location ID: 464351



Photo 3 – Fiberglass Vault – Capacity has faded no longer legible



Photo 4 – Recycle Pump containment - Oily Waste and Wildlife protection devices not adequate.

Inspection Photos

Location Name: Everitt 14-32 and Pevler 14-22 Tank Battery

Location ID: 464351



Photo 5 – Unused Supply/Volume Vessel