

## Inspection Photos

Location Name: DF Ranch 8-15, 15-12, 42, 44 Tank Battery

Location ID: 4611771



Photo 1 – Tank Battery

Photo 2 – North West Tank missing Contents and Capacity, NFPA label is peeling off.

## Inspection Photos

Location Name: DF Ranch 8-15, 15-12, 42, 44 Tank Battery

Location ID: 4611771



**Photo 3 – South Tanks missing capacity and NFPA labels are peeling**



**Photo 4 – Recycle Pump containment - Oily Waste and Wildlife protection devices not adequate**

## Inspection Photos

Location Name: DF Ranch 8-15, 15-12, 42, 44 Tank Battery

Location ID: 4611771



**Photo 5 – Stained Soil at 2-Phase Separator**



**Photo 6 – Stained Soil at 2-Phase Separator**