



## Inspection Photos Location #335688



3 production tanks missing information



Master valve is leaking

# Inspection Photos Location #335688



**Staining under master valve**