



WELL SITE INSPECTION FORM



WELL NAME Intermountain Oil/Gear
OPERATOR Roberts #1
LOCATION NWNE 13-9N-54W
FIELD Cedar Creek

API NUMBER 05 - 075 - 9161
PERMIT NUMBER ~~86-908~~ 87-290
COUNTY Logan
INSPECTOR Sp

AL/PA/DA INSPECTION RESULTS:

PASS(Y) ☒ FAIL(N) ☐ DATE 8/28/88

WELL STATUS:

FN ☐ FD ☐ WO ☐DATE OF INSPECTION BEFORE/DURING DRILLING 6/3/87

CASING SIZE 8 5/8 DEPTH SET 120 KB CMT VOL 75 SXS WOC ☐
CONSISTENT WITH APD CASING PROGRAM? ☐ RETURNS good
RIG Geor 2 BOP'S ☐ CONTACT ☐

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION ☐

PIPE SET? ☐ COMPLETION RIG/ACTIVITY ☐
DRILLING PITS: CLOSED ☐ OPEN ☐ WELLHEAD SYSTEM INSTALLED ☐
TANK ID: YES ☐ NO ☐ NA ☐ WELL SIGN: YES ☐ NO ☐
SKIM PIT: ☐ gal TANKS: (☐) ☐ bbls
EQUIPMENT ☐
BRADENHEAD PRESSURE ☐ FLUID: NO ☐ YES ☐ TYPE ☐
METER RUN: YES ☐ NO ☐ WELL STATUS: PR ☐ TA ☐ SI ☐ WELL CAT 3- ☐

AL/PA/DA INSPECTION

DATE PLUGGED: ☐ DATE PERMIT EXPIRED: ☐
HOLE PLUGGED: YES ☒ NO ☐ PITS BACKFILLED: YES ☒ NO ☐
MATERIAL BURIED: YES ☒ NO ☐ NA ☐ SITE CLEAN: YES ☒ NO ☐
BOND RELEASE OK: YES ☒ NO ☐ FED ☐ HOLE MARKER: YES ☐ NO ☒

DATE OF SAFETY/STATUS INSPECTION ☐

COMMENTS 1/14/87 Nothing
5/27/87 Nothing - permit refilled 5/13/87
6/9/87 Dry hole 20+10 - open pit
7/15/87 Open pits
4/14/88 pits currently being backfilled
8/28 OK