

Inspection Photos
Location Name: Grant #4
Location ID: 311319




Photo 1 WH sign

Photo 2 wellsite

Inspection Photos
Location Name: Grant #4
Location ID: 311319




Photo 3 WH

Photo 4 Leak and paraffin appear to be cleaned up

Inspection Photos
Location Name: Grant #4
Location ID: 311319



Photo 5 PU

Photo 6 produced water tank appears to be in the process of being removed/replaced

Inspection Photos
Location Name: Grant #4
Location ID: 311319



Photo 7 ECDs, Horiz. Heated separator

Photo 8 Vert. sep. gas meter run

Inspection Photos
Location Name: Grant #4
Location ID: 311319



Photo 9 TB sign

Photo 10 TB

Inspection Photos
Location Name: Grant #4 & Grant TB
Location ID: 311319



Photo 11 produced water tank compressor house

Photo 12 trash in compressor house