

**Inspection Photos**  
**Location Name: Meredith #2**  
**Location ID: 333126**



**Photo 1 WH sign**

**Photo 2 WH**

Inspection Photos  
Location Name: Meredith #2  
Location ID: 333126



Photo 3 TB sign

Photo 4 TB

**Inspection Photos**  
**Location Name: Meredith #2**  
**Location ID: 333126**



**Photo 5 Stained soil under crude oil tank valve**

**Photo 6 Heated Horiz. Sep.**

Inspection Photos  
Location Name: Meredith #2  
Location ID: 333126



**Photo 7 Electric panel, transformers and meter box  
Debris/dead weeds**

**Photo 8 Unused meter box and exposed wires.**

**Inspection Photos**  
**Location Name: Meredith #2**  
**Location ID: 333126**



**Photo 9 old Compressor house debris/ dead weeds**

**Photo 10 unused old compressor**