

Inspection Photos
Location Name: DOW-65N63W /28SWSE
Location #: 331414



Photo #1
DOW 34-28 (05-123-21882) Wellsite
Plugged & Abandoned | PA
~ 15 yds.
Appears to be cut & capped
Reclamation progressing



Photo #2
DOW 34-28 Battery
Inactive | Shut-down
Well: Plugged & Abandoned | PA
Appears in process of dismantling