

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402243498

Date Received:

11/19/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 52530

Name of Operator: MAGPIE OPERATING INC

Address: 2707 SOUTH COUNTY RD 11

City: LOVELAND State: CO Zip: 80537

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Warner, Ryan

970-669-6308

magpieoil@yahoo.com

Warner, Ross

ross.magpieoil@gmail.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696501070

Inspection Date: 11/14/2019

FIR Submit Date: 11/14/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: MAGPIE OPERATING INC

Company Number: 52530

Address: 2707 SOUTH COUNTY RD 11

City: LOVELAND State: CO Zip: 80537

LOCATION - Location ID: 307182

Location Name: STATE ANDERSON-65N68W Number: 36NWNE County: \_\_\_\_\_

Qtrqtr: NWNE Sec: 36 Twp: 5N Range: 68W Meridian: 6

Latitude: 40.361264 Longitude: -104.952287

FACILITY - API Number: 05-069-00 Facility ID: 307182

Facility Name: STATE ANDERSON-65N68W Number: 36NWNE

Qtrqtr: NWNE Sec: 36 Twp: 5N Range: 68W Meridian: 6

Latitude: 40.361264 Longitude: -104.952287

CORRECTIVE ACTIONS:

1 CA# 134546

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).

Date: 12/20/2019

Response: CA COMPLETED

Date of Completion: 11/15/2019

Operator  
Comment:

Berms have been repaired. Additional roadbase brought in to increase capacity.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**2** CA# 134547

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 12/20/2019

Response: CA COMPLETED

Date of Completion: 11/15/2019

Operator Comment: All valves and fittings throughout the location have been inspected and tightened. Inspection frequency will be increased.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**3** CA# 134548

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.

Date: 12/20/2019

Response: CA COMPLETED

Date of Completion: 11/15/2019

Operator Comment: Any and all oily waste was removed, contained and will be disposed of in accordance with 907.e. at a commercial solid waste disposal facility.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Crew on site within 24 hours of inspection. Site repaired. Internal location inspection frequency will be increased.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ross Warner

Signed: \_\_\_\_\_

Title: Compliance

Date: 11/19/2019 2:45:13 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402243554	siteberm
402243555	phototank
402243556	phototankberm

Total Attach: 3 Files