

Inspection Photos
Location Name: Miller 1-17
Location ID: 328938



Photo 1 WH sign

Photo 2 Gas line to drip pot appears to have been repaired/replaced