

Inspection Photos
Location Name: LAURA-65N63W /28SENE
Location #: 305671



Colorado Oil & Gas Conservation Commission
40.3725, -104.43372, 1367.0m, 189°
11/19/2019 04:21:02 PM

Photo #1
Laura 8-28 (05-123-23332) Wellsite
Plugged & Abandoned | PA
~ 15 yds.
Appears to be cut & capped
Reclamation progressing



Colorado Oil & Gas Conservation Commission
40.37269, -104.43336, 1367.0m, 274°
11/19/2019 04:22:30 PM

Photo #2
Laura 8-28 Battery site
Abandoned | Most equipment removed
Reclamation progressing
Unused Gas meter run