

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2019

Submitted Date:

11/20/2019

Document Number:

693801266

FIELD INSPECTION FORMLoc ID 316821 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10453

Name of Operator: PARADOX UPSTREAM LLC

Address: PO BOX 220

City: NATURITA State: CO Zip: 81422

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|-----------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Hankins, Neil | 970-428-2742 | davidh@paradoxresources.com | |
| Miller, Mandy | 970-739-3786 | mandym@paradoxresources.com | |
| Browning, Chuck | 970-433-4139 | chuck.browning@state.co.us | Field Inspector |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 261300 | WELL | TA | 01/01/2017 | GW | 113-06088 | FOSSIL FEDERAL 2-20 | TA |

General Comment:

MIT to maintain SI/TA status.

Location**Lease Road:**

| | | | |
|-------------------|--------|-------|--|
| Type | Main | | |
| comment: | | | |
| Corrective Action | | Date: | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | Date: | |

Overall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 435-587-2237 or 911

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-----------------------------------|-----|-------|-----------------|
| | | | corrective date |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | |
|-----------------------|-----|-------|
| Type: Bird Protectors | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|-----------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CONDENSATE | 1 | 100 BBLs | PBV STEEL | | 38.060987,-108.656834 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|--|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 261300 | Type: | WELL | API Number: | 113-06088 | Status: | TA | Insp. Status: | TA |
| Idle Well | | | | | | | | | |
| Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned Reminder: _____ | | | | | | | | | |
| Comment: MIT to maintain SI/TA status. Pressured casing to 360 psi. Hold for 15 min. Final pressure 353 psi. -7 psi loss. OK Test witnessed by COGCC using gauge on wellhead. No chart recorder. | | | | | | | | | |
| Corrective Action: _____ Date: _____ | | | | | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | Pass | Gravel | Pass | | | |
| Gravel | Pass | Ditches | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------------------|---|
| 693801270 | Inspection photos 11/19/2019 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4993183 |