

Inspection Photos
Location Name: Surprise-Damfino S6 Pad
Location ID: 416625



Photo 1. Overview of location facing southeast.



Photo 2. Rills in cut slope. Sediment migrating onto location.



Inspection Photos
Location Name: Surprise-Damfino S6 Pad
Location ID: 416625



Photo 3. Rills in cut slope. Sediment migrating onto location.



Photo 4. Overview of expanded portion of location facing southwest.

