

Inspection Photos
Location Name: Kodak South FD Pad 28-222HN
Location ID: 306149



Colorado Oil and Gas Conservation Commission
40.45372, -104.864, 1429.6m, 229°
Nov 20, 2019 11:52:23

Photo 1: Location Signs at Entrance



Photo 2: Location from entrance

Inspection Photos
Location Name: Kodak South FD Pad 28-222HN
Location ID: 306149



Photo 3: Wellhead Sign



Photo 4: Wellhead

Inspection Photos
Location Name: Kodak South FD Pad 28-222HN
Location ID: 306149



Photo 5: Wellhead Sign



Photo 6: Wellhead

Inspection Photos
Location Name: Kodak South FD Pad 28-222HN
Location ID: 306149



Photo 7: Wellhead Sign



Photo 8: Wellhead

Inspection Photos

Location Name: Kodak South FD Pad 28-222HN

Location ID: 306149



Photo 9: Wellhead Sign



Photo 10: Wellhead

Inspection Photos

Location Name: Kodak South FD Pad 28-222HN

Location ID: 306149



Photo 11: Wellhead Sign



Photo 12: Wellhead

Inspection Photos

Location Name: Kodak South FD Pad 28-222HN

Location ID: 306149




Photo 13: Stained soil, Unused equipment, trash



Photo 14: Wellhead Sign

Inspection Photos
Location Name: Kodak South FD Pad 28-222HN
Location ID: 306149



Photo 15: Wellhead



Photo 16: Stained soil

Inspection Photos

Location Name: Kodak South FD Pad 28-222HN

Location ID: 306149



Photo 17: Wellhead Sign



Photo 18: Wellhead

Inspection Photos
Location Name: Kodak South FD Pad 28-222HN
Location ID: 306149



Photo 19: Wellhead Sign



Photo 20: Wellhead

Inspection Photos
Location Name: Kodak South FD Pad 28-222HN
Location ID: 306149



Colorado Oil and Gas Conservation Commission
40.45255, -104.86407, 1426.1m, 27°
Nov 20, 2019 12:33:10

Photo 21: Unused equipment



Colorado Oil and Gas Conservation Commission
40.45253, -104.86407, 1426.1m, 21°
Nov 20, 2019 12:33:19

Photo 22: Trash

Inspection Photos
Location Name: Kodak South FD Pad 28-222HN
Location ID: 306149



Photo 25: No NFPA Placard



Photo 26: No NFPA Placard

Inspection Photos

Location Name: Kodak South FD Pad 28-222HN

Location ID: 306149



Photo 27: Tanks that DO NOT contain NFPA placard

