

Inspection Photos
Location Name: Jones 1-11
Location ID: 316760



Photo 1. Overview of location taken facing east.



Photo 2. Tubing stored at wellhead.



Inspection Photos
Location Name: Jones 1-11
Location ID: 316760



Photo 3. Stained soil at pump jack base.



Photo 4. Stained soil at wellhead.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Jones 1-11
Location ID: 316760



Photo 5. Stained soil at loadout valve.



Photo 6. Stained soil at parking for loadout.



Inspection Photos
Location Name: Jones 1-11
Location ID: 316760



Photo 7. Stained soil at loadout valve.



Photo 8. Stained soil at loadout valve.



Inspection Photos
Location Name: Jones 1-11
Location ID: 316760



Photo 9. Stained soil at loadout valve.



Photo 10. Overview of tank battery taken facing northwest.

