

Inspection Photos

11/06/2019

Operator: MARALEX RESOURCES INC - 53255

Location ID: 312608

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312608




Photo 1: 2017 COGIS aerial imagery. Photo shows overview of the location (blue dot, top left), and the access road



Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312608



Photo 2: 1988 USGS aerial imagery. Photo shows the access road did not exist prior to oil and gas disturbance.

Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312608



Photo 3: Photo taken from the north end of the location, facing south. Photo shows recent reclamation activities appear to have been conducted. A follow-up inspection will be conducted during a future growing season to determine compliance with reclamation requirements.

Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312608



Photo 4: Photo taken from the north end of the location facing east. Photo shows reclamation activities have not been conducted along the access road.

Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312608



Photo 5: Photo taken from the access road facing east. Photo shows reclamation activities have not been conducted along the access road.