

**Inspection Photos**  
**Location Name: HSR- Gutteresen A 10-3**  
**Location ID: 329958**



**Photo #1 Wellhead & Sign**

**Inspection Photos**  
**Location Name: HSR- Guttersen A 10-3**  
**Location ID: 329958**



**Photo #2 Tank battery & Weeds. On 10/24/19**



**Photo #3 Tank battery & Weeds. On 11/20/19**

**Inspection Photos**  
**Location Name: HSR- Guttersen A 10-3**  
**Location ID: 329958**



**Photo #4 Weeds in tank battery. On 10/24/19**



**Photo #5 Weeds in tank battery. On 11/20/19**

**Inspection Photos**  
**Location Name: HSR- Guttersen A 10-3**  
**Location ID: 329958**



**Photo #6 Weeds in tank battery. On 10/24/19**



**Photo #7 Weeds in tank battery. On 11/20/19**

**Inspection Photos**  
**Location Name: HSR- Guttersen A 10-3**  
**Location ID: 329958**



**Photo #8 Weeds in tank battery. On 10/24/19**



**Photo #9 Weeds in tank battery. On 11/20/19**

**Inspection Photos**  
**Location Name: HSR- Gutteresen A 10-3**  
**Location ID: 329958**



**Photo #10 Weeds around Separator. On 10/24/19**



**Photo #11 Weeds around Separator. On 11/20/19**