

Inspection Photos
Location Name: HSR-Guttersen "A" 9-3
Location ID: 329957



Photo #1 Weeds around ECD. On 10/24/19



Photo #2 Weeds around ECD. On 11/20/19

Inspection Photos
Location Name: HSR-Guttersen "A" 9-3
Location ID: 329957



Photo #3 Weeds around Separator. On 10/24/19



Photo #4 Weeds around Separator. On 11/20/19

Inspection Photos
Location Name: HSR-Guttersen "A" 9-3
Location ID: 329957



Photo #5 Weeds around Meter Run/ Separator. On 10/24/19



Photo #6 Weeds around Meter Run/ Separator. On 11/20/19

Inspection Photos
Location Name: HSR-Guttersen "A" 9-3
Location ID: 329957



Photo #9 Weeds in Tank Battery. On 10/24/19



Photo #10 Weeds in Tank Battery. On 11/20/19

Inspection Photos
Location Name: HSR-Guttersen "A" 9-3
Location ID: 329957



Colorado Oil and Gas Conservation Commission
40.2524, -104.53109, 4652.4ft, 113°
10/24/2019 09:33:12 AM

Photo #11 Weeds in Tank Battery. On 10/24/19



Colorado Oil and Gas Conservation Commission
40.25242, -104.53106, 4630.9ft, 154°
11/20/2019 11:02:51 AM

Photo #12 Weeds in Tank Battery. On 11/20/19

Inspection Photos
Location Name: HSR-Guttersen "A" 9-3
Location ID: 329957



Colorado Oil and Gas Conservation Commission
40.25226, -104.53099, 4656.4ft, 33°
10/24/2019 09:34:02 AM



Colorado Oil and Gas Conservation Commission
40.25223, -104.53094, 4635.5ft, 34°
11/20/2019 11:02:08 AM

Photo #13 Weeds in Tank Battery. On 10/24/19

Photo #14 Weeds in Tank Battery. On 11/20/19