

Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 1. Overview of location taken facing southwest.



Photo 2. Overview of location taken facing northwest



Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 3. Rills leaving location, site degradation.



Photo 4. Rills leaving location, site degradation.

Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 5. Rills leaving location and traveling to access road.



Photo 6. 1 of 3 2" unmarked steel risers.

Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 7. 2 of 3 2" unmarked risers.



Photo 8. 3 - 1" unmarked risers.

Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 9. Example of missing tank labels, site degradation.



Photo 10. Example of missing tank labels, site degradation.



Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 11. Erosion leaving location traveling to access road.



Photo 12. Erosion rill leaving access road.

