

Inspection Photos
Location Name: State Anderson 1-36
Location ID: 307182



Wellhead

Inspection Photos
Location Name: State Anderson 1-36
Location ID: 307182



Colorado Oil And Gas Conservation Commission
40.36114, -104.95185, 1478.0m
11/14/2019 11:00:02 AM

Crude oil tank berm on 11/14/19



Colorado Oil And Gas Conservation Commission
40.36131, -104.95193, 1479.0m
11/20/2019 8:40:27 AM

Crude oil tank berm on 11/20/19

Inspection Photos
Location Name: State Anderson 1-36
Location ID: 307182



West crude oil tank leaks and stained soil on 11/14/19



West crude oil tank leaks and stained soil on 11/20/19

Inspection Photos
Location Name: State Anderson 1-36
Location ID: 307182



East crude oil tank leaks on 11/14/19



East crude oil tank leaks on 11/20/19