

Inspection Photos

Loc#334583

Operator: Caerus

Inspection Number: 692401566

Inspection Date: 11/1/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to West.

November 1, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Parker Ranch Loc#334583



Photo#2:

Views of BMP needing repair at North side of entry on East end of Location.

November 1, 2019



Photo#3:
Views of interim Reclamation areas.

November 1, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Parker Ranch Loc#334583



Photo#3:
Aerial COGCC Map view of Location.

November 1, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Parker Ranch Loc#334583