

Construction and Stormwater Inspection

November 19, 2019

Operator: NICKEL ROAD OPERATING LLC #10669

Location ID: 465636

Inspection Document #: 697500846

Weld County, CO

NWSW Section 11 T7N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: ELDER /PAD
Location ID: 465636



Photo 1. Photo taken from the entrance of the location off HWY 14, facing East. Photo illustrates no vehicle track out issues. Operator has not yet installed the planned vehicle tracking device BMPs.



Photo 2. Photo taken from the entrance of the location off HWY 14, facing West. See comments under Photo 1.



Photo 3. Photo taken from the entrance of the location. Photo illustrates Operator signage.

Inspection Photos
Location Name: ELDER /PAD
Location ID: 465636



Photo 4. Photo taken from the entrance of the location, facing North. Photo illustrates Operator in process of constructing the access road. A ditch BMP and surface roughening BMP were implemented on either side of the access road during construction operations.