

Inspection Photos
Location Name: Lowell-Paul Dairy 1-33
Location ID: 322671



Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos
Location Name: Lowell-Paul Dairy 1-33
Location ID: 322671



Photo 3: Tank Battery Sign



Photo 4: Tank Battery



Inspection Photos
Location Name: Lowell-Paul Dairy 1-33
Location ID: 322671



Photo 5: Separator not anchored; trash



Photo 6: Trash

