

Inspection Photos

Loc#467526

Operator: Sandridge

Inspection Number: 692401601

Inspection Date: 11/6/19





Photo#1:
Overview of Location to North.

November 6, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Spicer Loc#467526



Photo#2:
Topsoil stockpile.



Photo#3:
View along Cut.

November 6, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Spicer Loc#467526



Photo#4:
Ditch, berm..



Photo#5:
Silt fence.

November 6, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Spicer Loc#467526



Photo#6:
Work along road entry.

November 6, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Spicer Loc#467526