

Inspection Photos

API#057-06462

Operator: Farleigh Oil

Inspection Number: 692401633

Inspection Date: 11/6/19





Photo#1:

View of Location to Northwest. Note areas bare of vegetation along road area leading into fenced land farm exclusion area.

November 6, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Farleigh Oil PA Silver Spur API#057-06462



Photo#2:
Land farm area 8/23/17.



Photo#3:
Land farm area 9/13/18.

November 6, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Farleigh Oil PA Silver Spur API#057-06462



Photo#4:
Land farm area 11/6/19.



Photo#5:
Land farm area 11/6/19

November 6, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Farleigh Oil PA Silver Spur API#057-06462