

Inspection Photos  
Operator: Rim Operating  
Location/API #: 067-06515  
Date: 11-12-2019



Photo 1. View of the project area from the western edge facing center.





Photo 2. View of the northern fill slope from the northwestern corner facing eastward. Revegetation is progressing, largely with grasses such as smooth brome and western wheatgrass.





Photo 3. View of reference area, comprised of sagebrush and pinyon juniper woodland.