

Inspection Photos
Location Name: Dutch Lake 9-11H
Location ID: 422932




Photo 1 – Wellheads, Unused Equipment/Tubing



Photo 2 – Tank Battery

Inspection Photos
Location Name: Dutch Lake 9-11H
Location ID: 422932



Photo 3 – Unmarked 1” and 2” Risers




Photo 4 – Unused Equipment