

**Inspection Photos**  
**Location Name: Dutch Lake 17-25H**  
**Location ID: 422842**



**Photo 1 – Pumping Unit**



**Photo 2 – Tank Battery**

Inspection Photos  
Location Name: Dutch Lake 17-25H  
Location ID: 422842




Photo 3 – Stained Soil at Wellhead



Photo 4 – Unmarked 3" Riser at Pumping Unit

**Inspection Photos**  
**Location Name: Dutch Lake 17-25H**  
**Location ID: 422842**



**Photo 5 – Unmarked 1” Riser North of Gas Meter Houses**



**Photo 6 – Unused Piping on Southside of Location**