

**Inspection Photos**  
**Location Name: Dutch Lake 23-34H**  
**Location ID: 423223**




**Photo 1 – Pumping Unit and Tank Battery**



**Photo 2 – Unmarked 3" Riser**

**Inspection Photos**  
**Location Name: Dutch Lake 23-34H**  
**Location ID: 423223**



**Photo 3 – Unmarked 1” Riser and Unused Chemical Tank at Southside of Pumping Unit**

**Photo 4 – Missing Capacity Label**

Inspection Photos  
Location Name: Dutch Lake 23-34H  
Location ID: 423223



Photo 5 – Unused Tubing at Pumping Unit



Photo 6 – Unused Tubing and Rods at Pumping Unit