

Inspection Photos
Location Name: North Platte /24-24 Pad
Location #: 310065



Photo #1

North Platte 24-24 (05-123-25827) Wellsite
Temporarily Abandoned | TA



Photo #2

North Platte 24-24 Wellsite
Temporarily Abandoned | TA
Access road sign

Inspection Photos
Location Name: North Platte /24-24 Pad
Location #: 310065



Photo #3
North Platte 23-24, 24-24 Battery
Inactive | Shut-down