

Inspection Photos
Location Name: State 12-7
Location ID: 324701



Photo 1. Overview of location taken facing east.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: State 12-7
Location ID: 324701



Photo 2. Example of sandy road.



Photo 3. Example of overgrown/difficult to locate road.

