

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/22/2019

Submitted Date:

11/22/2019

Document Number:

697000232

FIELD INSPECTION FORM

Loc ID 442433 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10634
Name of Operator: P O & G OPERATING LLC
Address: 5847 SAN FELIPE SUITE 3200
City: HOUSTON State: TX Zip: 77057

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hudson, Glen	713-589-8186	glenn_hudson@pogresources.com	Engineer

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442431	WELL	PR	11/22/2015	LO	017-07803	Harley 6H	PR

General Comment:

Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Dirt road through pasture		
Corrective Action		Date:	

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:	Stickers on chemical drum		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Tubing stored next to unit		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:	Sentry 320		
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Electric panel, control panel, cathodic rectifier and chemical tank w/containment		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 442431 Type: WELL API Number: 017-07803 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Central tank battery for \(Pepper 1 and Harley 6H\) 865' N @ 38.863970/-102.362950](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT