

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/22/2019

Submitted Date:

11/22/2019

Document Number:

697000236

FIELD INSPECTION FORM

Loc ID 432263 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10634
Name of Operator: P O & G OPERATING LLC
Address: 5847 SAN FELIPE SUITE 3200
City: HOUSTON State: TX Zip: 77057

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hudson, Glen	713-589-8186	glenn_hudson@pogresources.com	Engineer

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432278	WELL	PR	05/17/2018	OW	017-07746	Harley 4	PR

General Comment:

Routine Inspection

Location

Lease Road:			
	Type Access		
comment:	Trail through farm ground		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
	Type WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Electric panel, cathodic rectifier and telemetry equipment		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Lufkin 160		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 432278 Type: WELL API Number: 017-07746 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Central tank battery for \(Harley 1, 3, 4\) 2100' N @ 38.863970/-102.362950](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT