

RGU 33-32-198  
API: 05-103-10707  
Inspection: 679706 266



39.91786, -108.41194, 6462.7ft, 111°  
11/22/2019 02:30:35 PM

**Photo 1. Location.**

RGU 33-32-198  
API: 05-103-10707  
Inspection: 679706 266



39.91758, -108.41111, 6470.0ft, 58°  
11/22/2019 02:32:10 PM

Photo 2. Separator.

RGU 33-32-198  
API: 05-103-10707  
Inspection: 679706 266



Photo 3. Tanks.