

Inspection Photos  
Location Name: Spade 1-12  
Location ID: 319612



Photo 1: Tank Battery Sign



Photo 2: Tank Battery



**Inspection Photos**  
**Location Name: Spade 1-12**  
**Location ID: 319612**



**Photo 3: Holes repaired**



**Photo 4: Holes repaired, stained soil removed**



**Inspection Photos**  
**Location Name: Spade 1-12**  
**Location ID: 319612**



**Photo 5: Unused equipment removed**



**Photo 6: Stained soil removed**





**Inspection Photos**  
**Location Name: Spade 1-12**  
**Location ID: 319612**



**Photo 7: Stained soil removed**



**Photo 8: Wellhead Sign**

**Inspection Photos**  
**Location Name: Spade 1-12**  
**Location ID: 319612**




**Photo 9: Wellhead**



**Photo 10: Stained soil**



**Inspection Photos**  
**Location Name: Spade 1-12**  
**Location ID: 319612**



**Photo 11: Stained Soil**