

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402237739  
Receive Date:  
11/25/2019

Report taken by:  
PETER GINTAUTAS

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: <u>KERR MCGEE OIL &amp; GAS ONSHORE LP</u>	Operator No: <u>47120</u>	<b>Phone Numbers</b>
Address: <u>P O BOX 173779</u>		
City: <u>DENVER</u>	State: <u>CO</u>	Phone: <u>(970) 336-3500</u>
	Zip: <u>80217-3779</u>	Mobile: <u>( )</u>
Contact Person: <u>Phil Hamlin</u>	Email: <u>Phil_Hamlin@oxy.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

**PROJECT INFORMATION**  
Remediation Project #: 205 Initial Form 27 Document #: 1008388

**PURPOSE INFORMATION**

<input type="checkbox"/> 901.e. Sensitive Area Determination	<input checked="" type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water
<input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure	<input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b.
<input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation	<input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project
<input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste	<input type="checkbox"/> Rule 906.c.: Director request
<input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure	<input type="checkbox"/> Other _____

**SITE INFORMATION** N Multiple Facilities ( in accordance with Rule 909.c. )

Facility Type: <u>LOCATION</u>	Facility ID: <u>318170</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>SARATOGA-64N66W 33SWSW</u>	Latitude: <u>40.263639</u>	Longitude: <u>-104.788361</u>	
	** correct Lat/Long if needed: Latitude: <u>40.263023</u>	Longitude: <u>-104.788298</u>	
QtrQtr: <u>SWSW</u>	Sec: <u>33</u>	Twp: <u>4N</u>	Range: <u>66W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

**SITE CONDITIONS**

General soil type - USCS Classifications SC Most Sensitive Adjacent Land Use Agriculture and Livestock

Is domestic water well within 1/4 mile? Yes Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? Yes

**Other Potential Receptors within 1/4 mile**

Water well located approximately 450 feet (ft) northeast, surface water located approximately 1,200 ft southwest, buildings located approximately 380 ft south, livestock located approximately 50 ft southwest, and groundwater at approximately 6 ft below ground surface (bgs).

# SITE INVESTIGATION PLAN

## TYPE OF WASTE:

- |   |  |  |
|---|--|--|
| <input checked="" type="checkbox"/> E&P Waste | <input type="checkbox"/> Other E&P Waste             | <input type="checkbox"/> Non-E&P Waste |
| <input type="checkbox"/> Produced Water       | <input type="checkbox"/> Workover Fluids             | _____                                  |
| <input checked="" type="checkbox"/> Oil       | <input type="checkbox"/> Tank Bottoms                |  |
| <input type="checkbox"/> Condensate           | <input type="checkbox"/> Pigging Waste               |  |
| <input type="checkbox"/> Drilling Fluids      | <input type="checkbox"/> Rig Wash                    |  |
| <input type="checkbox"/> Drill Cuttings       | <input type="checkbox"/> Spent Filters               |  |
|   | <input type="checkbox"/> Pit Bottoms                 |  |
|   | <input type="checkbox"/> Other (as described by EPA) | _____                                  |

## DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	GROUNDWATER	See attached data	Groundwater Samples/Lab Analysis
Yes	SOILS	Unknown	Soil Samples/Lab Analysis

## INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

On May 20, 1994, the well operator discovered a hole in the side of an oil tank at the Saratoga #1 tank battery. Approximately 92 barrels (bbls) of crude oil were released into the bermed tank area. An unknown volume of crude oil seeped out of the tank berm onto the adjacent lease road. Approximately 40 bbls of oil were recovered from within the tank battery berm and transferred to another production tank. Basin Exploration, Inc. performed the initial site assessment in May 1994. The release was initially reported to the Colorado Oil and Gas Conservation Commission (COGCC) on August 5, 1994 via written notification.

## PROPOSED SAMPLING PLAN

### Proposed Soil Sampling

Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

Details of the site assessment and remediation activities conducted by Basin Exploration, Inc. are summarized in a Spill Assessment and Remediation Status Report submitted to the COGCC on May 23, 1995.

In March 2005, three soil samples (MW01@12-15', MW02@12-15', and MW03@8-12') were collected from assessment soil borings MW01 through MW03 and submitted for laboratory analysis of total petroleum hydrocarbons (TPH). Laboratory analytical results indicated that the TPH concentration in soil sample MW01@12-15' exceeded the COGCC sensitive area allowable level of 1,000 milligrams per kilogram (mg/kg) at a concentration of 1,000 mg/kg. The soil samples were not analyzed for benzene, toluene, ethylbenzene, and total xylenes (BTEX) as the samples were collected prior to the April 1, 2009, COGCC rule changes.

### Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

Quarterly groundwater monitoring has been conducted at the site since March 2005.

### Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

### Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

### Soil

Number of soil samples collected 3  
Number of soil samples exceeding 910-1 1  
Was the areal and vertical extent of soil contamination delineated? No  
Approximate areal extent (square feet) 0

### NA / ND

-- Highest concentration of TPH (mg/kg) 5000  
NA Highest concentration of SAR           
BTEX > 910-1 Yes  
Vertical Extent > 910-1 (in feet) 15

### Groundwater

Number of groundwater samples collected 664  
Was extent of groundwater contaminated delineated? Yes  
Depth to groundwater (below ground surface, in feet) 6'  
Number of groundwater monitoring wells installed 33  
Number of groundwater samples exceeding 910-1 259

-- Highest concentration of Benzene (µg/l) 19000  
-- Highest concentration of Toluene (µg/l) 230  
-- Highest concentration of Ethylbenzene (µg/l) 2900  
-- Highest concentration of Xylene (µg/l) 21000  
NA Highest concentration of Methane (mg/l)         

### Surface Water

0 Number of surface water samples collected  
         Number of surface water samples exceeding 910-1  
If surface water is impacted, other agency notification may be required.

## OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Petroleum hydrocarbon impacts to groundwater are present in monitoring wells in the adjoining agricultural field northwest of the tank battery facility. The monitoring well locations and general site layout are depicted in the Site Map attached as Figure 1.

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)          Volume of liquid waste (barrels)         

Is further site investigation required?

# REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No \_\_\_\_\_

## SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Please refer to the Form 27 submitted to the COGCC on May 11, 2015. Details of the site assessment and remediation activities conducted by Basin Exploration, Inc. are summarized in a Spill Assessment and Remediation Status Report submitted to the COGCC on May 23, 1995.

Based on the March 2005 subsurface soil assessment, petroleum hydrocarbon impacts to soil remain in place in the vicinity of soil boring/monitoring well MW01.

## REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Remedial options are under evaluation.

## Soil Remediation Summary

### In Situ

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Air sparge / Soil vapor extraction  
\_\_\_\_\_ Natural Attenuation  
\_\_\_\_\_ Other \_\_\_\_\_

### Ex Situ

\_\_\_\_\_ Excavate and offsite disposal  
\_\_\_\_\_ If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_  
\_\_\_\_\_ Name of Licensed Disposal Facility or COGCC Facility ID # \_\_\_\_\_  
\_\_\_\_\_ Excavate and onsite remediation  
\_\_\_\_\_ Land Treatment  
\_\_\_\_\_ Bioremediation (or enhanced bioremediation)  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Other \_\_\_\_\_

## Groundwater Remediation Summary

Yes \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
No \_\_\_\_\_ Chemical oxidation  
No \_\_\_\_\_ Air sparge / Soil vapor extraction  
Yes \_\_\_\_\_ Natural Attenuation  
Yes \_\_\_\_\_ Other \_\_\_\_\_  
\_\_\_\_\_ Groundwater Removal and  
\_\_\_\_\_ Microbial/Nutrient Application

## GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

In August 2019, replacement groundwater monitoring wells MW03R and MW15R were installed at the site. Boring logs with well completion diagrams are included as an attachment.

Groundwater monitoring wells MW01R, MW02, MW03R, MW04, MW05, MW07, MW09 through MW14, MW15R, MW17 through MW20, MW21R, and MW22 through MW29 are sampled on a quarterly basis and submitted for laboratory analysis for BTEX by United States Environmental Protection Agency Method 8260D. The monitoring well locations are depicted on Figure 1. The Groundwater Elevation Contour Map generated using the September 2019 survey data is provided as Figure 2. The groundwater analytical results are summarized in Table 1, and the laboratory analytical reports for the June 2019 and September 2019 groundwater monitoring events are attached.

Groundwater monitoring will continue on a quarterly basis until a No Further Action status request is warranted.

## REMEDIATION PROGRESS UPDATE

### PERIODIC REPORTING

**Frequency:**  Quarterly  Semi-Annually  Annually  Other \_\_\_\_\_

**Report Type:**  Groundwater Monitoring  Land Treatment Progress Report  O&M Report  
 Other \_\_\_\_\_

### WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards \_\_\_\_\_

E&P waste (solid) description \_\_\_\_\_

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: \_\_\_\_\_

Volume of E&P Waste (liquid) in barrels \_\_\_\_\_

E&P waste (liquid) description \_\_\_\_\_

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: \_\_\_\_\_

## REMEDIATION COMPLETION REPORT

### REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

Do all soils meet Table 910-1 standards? No

Does the previous reply indicate consideration of background concentrations? \_\_\_\_\_

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? No

Does Groundwater meet Table 910-1 standards? No

Is additional groundwater monitoring to be conducted? Yes

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The Kerr-McGee production facility remains at the site.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim?  Final?

Did the Surface Owner approve the seed mix? \_\_\_\_\_

If NO, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

## IMPLEMENTATION SCHEDULE

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. \_\_\_\_\_

Actual Spill or Release date, if known. 05/20/1994

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 05/20/1994

Date of commencement of Site Investigation. 07/14/1994

Date of completion of Site Investigation. 03/25/2019

### REMEDIAL ACTION DATES

Date of commencement of Remediation. 05/20/1994

Date of completion of Remediation. \_\_\_\_\_

### SITE RECLAMATION DATES

Date of commencement of Reclamation. \_\_\_\_\_

Date of completion of Reclamation. \_\_\_\_\_

### OPERATOR COMMENT

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Phil Hamlin

Title: Senior Environmental Rep.

Submit Date: 11/25/2019

Email: Phil\_Hamlin@oxy.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: PETER GINTAUTAS

Date: 11/25/2019

Remediation Project Number: 205

### COA Type

### Description

<u>COA Type</u>	<u>Description</u>

### **Attachment Check List**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

<u>Att Doc Num</u>	<u>Name</u>
402237739	FORM 27-SUPPLEMENTAL-SUBMITTED
402237762	LOGS
402238680	GROUND WATER ELEVATION MAP
402238684	SITE MAP
402241192	ANALYTICAL RESULTS

Total Attach: 5 Files

### **General Comments**

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
	Submit reports of site investigation and progress of remediation including results of sampling and analysis on an annual basis or more often until remediation is closed.	11/25/2019

Total: 1 comment(s)