

# *Inspection Photos*

*Loc#311534*

*Operator: Terra*

*Inspection Number: 692401651*

*Inspection Date: 11/22/19*





Photo#1:  
Overview of Location to Southwest.

November 22, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Federal Rulision Loc#311534 PC



Photo#2:  
North side of access road at entry.



Photo#3:  
South side of access road at entry.

November 22, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Federal Rulision Loc#311534 PC



Photo#4:  
Views of Cut slope.

November 22, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Federal Rulision Loc#311534 PC



Photo#5:  
Topsoil Stockpile.



Photo#6:  
Check dams, wattles along North perimeter.

November 22, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Federal Rulision Loc#311534 PC



Photo#7:  
Flexible drain on East fill slope.



Photo#8:  
Sediment retention area.

November 22, 2019