

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/25/2019

Submitted Date:

11/26/2019

Document Number:

696101612**FIELD INSPECTION FORM**Loc ID 413457 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		EHSRC@bonanzacrk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412513	WELL	SI	04/01/2019	OW	123-30597	NORTH PLATTE 31-34	SI
423532	WELL	SI	04/01/2019	GW	123-33613	North Platte 32-34	SI

**General Comment:**

This is a WELL inspection.  
Well(s): 2: Shut-In | SI.  
Battery: Shut-down | Inactive.

Centralized Battery serves 2 Location IDs (413457, 413974).  
(Well(s): 4 ; 2: Shut-In | SI ; 2: Temporarily Abandoned | TA).  
(1: Other well associated w/ Location ID #413974 is connected to another Battery/Facility.)

Refer to Field Inspection Report Doc. #696101492 and/or Location ID #413457  
for Battery / Facility, Equipment info.

Follow-up to Field Inspection Report doc. #696101492 dated 10/30/2019.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type			
Comment:	Refer to Field Inspection Report Doc. #696101492 and/or Location ID #413457 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Prior insp: Sign with company & well name NOT posted at North Platte 31-34 wellsite. Refer to Rule 210.b. (60 Days). * Post sign with company & well name at North Platte 31-34 wellsite. Comply w/ Rule 210.b. Corrective Action date: 12/30/2019.  This insp: * Sign with company & well name NOW posted at North Platte 31-34 wellsite. See photos #1, 2.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type			
Comment:	Refer to Field Inspection Report Doc. #696101492 and/or Location ID #413457 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Bradenhead	# 2		corrective date
Comment:	2 - Wellsites: Appears plumbed to surface		
Corrective Action:		Date:	

Type: Plunger Lift	# 2	
Comment:	2 - Wellsites.	
Corrective Action:		Date:
Type:	#	
Comment:	Refer to Field Inspection Report Doc. #696101492 and/or Location ID #413457 for Battery / Facility, Equipment info.	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.363892,-104.413841
Comment:	Centralized Battery serves 2 Location IDs (413457, 413974). Refer to Field Inspection Report Doc. #696101492 and/or Location ID #413457 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 412513 Type: WELL API Number: 123-30597 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: Shut-In | SI. Observed production valves closed.  
COGCC records indicate last production: 03/2019.Corrective Action:  Date: Facility ID: 423532 Type: WELL API Number: 123-33613 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: Shut-In | SI. Observed production valves closed.  
COGCC records indicate last production: 03/2019.Corrective Action:  Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On MON 11/25/2019 at approximately 10:56 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC  Location Name: North Platte /32-34  Location ID: 413457  Well Names: North Platte 31-34, North Platte 32-34  API: 05-123-30597, 05-123-33613  Location County: Weld County, Colorado  Weather: Overcast &amp; dry.</p> <p>While there, I observed:  Well(s): 2: Shut-In   SI.  Battery: Shut-down   Inactive.</p> <p>Centralized Battery serves 2 Location IDs (413457, 413974).  (Well(s): 4 ; 2: Shut-In   SI ; 2: Temporarily Abandoned   TA).  (1: Other well associated w/ Location ID #413974 is connected to another Battery/Facility.)</p> <p>Refer to Field Inspection Report Doc. #696101492 and/or Location ID #413457 for Battery / Facility, Equipment info.</p> <p>Follow-up to Field Inspection Report doc. #696101492 dated 10/30/2019.  During this inspection, the following prior possible compliance issues appear to be addressed:  1.) Sign with company &amp; well name NOT posted at North Platte 31-34 wellsite.  Refer to Rule 210.b. (60 Days).  * Post sign with company &amp; well name at North Platte 31-34 wellsite.  Comply w/ Rule 210.b.  Corrective Action date: 12/30/2019.  * Sign with company &amp; well name NOW posted at North Platte 31-34 wellsite.  See photos #1, 2.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	11/26/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
696101613	Site photos	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4998879">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4998879</a>