

# *Inspection Photos*

*API#057-06487*

*Operator: Laramie*

*Inspection Number: 692401603*

*Inspection Date: 11/6/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to West.



Photo#1:  
Overview of Location to East.

November 6, 2019



Photo#3:  
Desiccated Canada & Russian thistle.



Photo#4:  
Desiccated Canada & Russian thistle.

November 6, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie AL Fugua API#057-06487