

Inspection Photos  
Location Name: Peterson PC LG 19-6  
Location ID: 422755



Photo 1 – Tank Battery




Photo 2 – Stained Soil at Wellhead, Unused Wellhead parts, Unmarked 2" Riser

Inspection Photos  
Location Name: Peterson PC LG 19-6  
Location ID: 422755




Photo 3 – Unused Stains and Containment and Tubing



Photo 4 – Stained Soil at Gas Engine