

# Construction and Stormwater Inspection

November 25, 2019

Operator: WHITING OIL & GAS CORPORATION- #96155

Location ID: 439542

Inspection Document #: 697500874

Weld County, CO

SENE Section 29 T10N R58W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Razor /29H Pad  
Location ID: 439542



**Photo 1.** Photo taken from the southern perimeter of location, facing West. Photo illustrates Operator was installing perimeter stormwater BMPs. Operator indicated that topsoil salvage operations would not start until the ditch and berm BMP were properly installed (i.e., berm was stabilized). Operator also indicated that sediment traps would also be installed in conjunction with the ditch and berm BMP.

Inspection Photos  
Location Name: Razor /29H Pad  
Location ID: 439542



**Photo 2.** Photo taken from the southern perimeter of location, facing East. Photo illustrates the first pass with plans to install a ditch and berm BMP.

Inspection Photos  
Location Name: Razor /29H Pad  
Location ID: 439542



**Photo 3.** Photo taken from the southeastern perimeter of location, facing North.  
See comments under Photo 2.