

Final Reclamation and Stormwater Inspection

November 25, 2019

Operator: WHITING OIL & GAS CORPORATION- #96155

Location ID: 330979

Inspection Document #: 697500876

Weld County, CO

NWNW Section 29 T10N R58W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: UHL #2
Location ID: 330979



Photo 1. Photo taken from the central well location, facing East. Photo illustrates Operator has performed Final Reclamation activities with the evidence of desirable vegetation establishment; however, well location will remain in process as there is not uniform vegetative growth reflective of reference area vegetative levels.



Photo 2. Photo taken from the central well location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: UHL #2
Location ID: 330979



Photo 3. Close up photo taken from the central well location. Photo illustrates the desirable vegetation establishment.

Inspection Photos
Location Name: UHL #2
Location ID: 330979



Photo 4. Photo taken from the eastern well location access road, facing West. Photo illustrates Operator has performed Final Reclamation activities with the evidence of desirable vegetation establishment; however, access road will remain in process as there is not uniform vegetative growth reflective of reference area vegetative levels.

Inspection Photos
Location Name: UHL #2
Location ID: 330979



Photo 5. Photo taken from the western tank battery location, facing South. Photo illustrates Operator has performed Final Reclamation activities; however, little establishment of desirable species was evident. There is a high abundance of Russian thistle; appears Operator is performing weed management as Russian thistle has been mowed.

Note: Equipment remains and appears to be out of service.



Photo 6. Close up photo taken from the equipment that remains at location.

Inspection Photos
Location Name: UHL #2
Location ID: 330979



Photo 7. Photo taken from the western tank battery location, facing East. See comments under Photo 5.