

# Final Reclamation and Stormwater Inspection

November 25, 2019

Operator: WHITING OIL & GAS CORPORATION- #96155

Location ID: 331145

Inspection Document #: 697500878

Weld County, CO

NWNE Section 30 T10N R58W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission


Department of Natural Resources

Inspection Photos  
Location Name: NELSON RANCHES #F-1  
Location ID: 331145



**Photo 1.** Photo taken from the eastern well location, facing West. Photo illustrates Operator has performed Final Reclamation activities with the evidence of desirable vegetation establishment. Well location appears reflective of reference area vegetative levels; however, the access road and tank battery location will remain in process. Operator will need to remove the perimeter fence.

Inspection Photos  
Location Name: NELSON RANCHES #F-1  
Location ID: 331145



**Photo 2.** Photo taken from the eastern well location, facing North. See comments under Photo 1. Reference area vegetation is illustrated outside of the red-dashed line.

Inspection Photos  
Location Name: NELSON RANCHES #F-1  
Location ID: 331145



**Photo 3.** Photo taken from a portion of the central access road, facing West. See comments under Photo 1.

Inspection Photos  
Location Name: NELSON RANCHES #F-1  
Location ID: 331145



**Photo 4.** Photo taken from the central tank battery location, facing West. See comments under Photo 1.