

Inspection Photos

API#103-09660

Operator: Caerus

Inspection Number: 692401624

Inspection Date: 11/8/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northeast.

November 8, 2019



Photo#2:
Depressions (subsidence) visible on West side of site.



Photo#3:
Depressions (subsidence) visible on West side of site.



November 8, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA BMU API#103-09660




Photo#4:
View East along access road into Location.



Photo#5:
View West along access road exiting Location.

November 8, 2019



Photo#6:
Storage area, view to West; inserts of ground conditions.

November 8, 2019