

Inspection Photos
Location Name: State Seventy Holes F-J-8HNB
Location ID: 433224



Photo 1 – Tank Battery



Photo 2 – Pumping Unit

Inspection Photos
Location Name: State Seventy Holes F-J-8HNB
Location ID: 433224




Photo 3 – Stained Soil and Oily Waste at Wellhead



Photo 4 – Oily Waste and Unused Rods